

Copy Done

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

23 April 1992

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED

APR 23 1992

DIVISION OF
OIL GAS & MINING

Dear Pamela:,

Re: Diversion Designs, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025,
Emery County, Utah

#2, #5

Attached with an M.E.C. letter dated 13 April 1992 were two copies of Plates 7-1C, 7-5 and 8-5C. Two ditches near the tippie area had been labeled D-10D and D-10aD. The angle of the loadout crossover belt was modified recently and this is shown on the updated Plates. (Also on Plate 2-4C submitted with NOV # N92-40-2-1). Two copies of updated pages 7-87, 7-87A and pages 49 thru 79 of Appendix 7-G were also attached. Table 7.2-10 indicates minimum diversion cross sections that meet Division requirements. These modifications were originally proposed as part of the abatement of NOV #N92-40-3-1. Please treat this as a proposed amendment to the PAP. On-site inspections should be easier to conduct using these values as minimum standards.

The copies of the proposed revised plates and pages are marked "DRAFT" to differentiate them from those previously approved. Four copies will be forwarded to the Division upon receipt of written approval. Please notify me if there are any questions or concerns regarding this matter.

Thank you,



Kimly C. Mangum, P.E.

cc: Co-Op Mining Co.